



READING

- 1- Insulating pot for electrodes.
- 2- Shortcircuit contactor.
- 3- Central conductor cooper.
- 4- Lateral conductor with cover.
- 5- Central insulating mechanized .
- 6- Bearing support.
- 7- Electrical equipment.
- 8- Motor.
- 9- Top cushion of spindle.
- 10- Complete level.
- 11- Glass tube of level.
- 12- Nut of the spindle.
- 13- Spindle.
- 14- Mobile electrode.
- 15- Bottom bearing of spindle.
- 16- Fixed electrode.
- 17- Limit switch.
- 18- Central cog belt.
- 19- Thermostat.
- 20- Central toothed pulley.
- 21- Level electric detector.
- 22- Central insulating tube.
- 23- Metallic support for insulating 5.
- 24- Intermediate toothed pulley (big).
- 25- Motor toothed pulley.
- 26- Motor cog belt.
- 27- Contactor coil.
- 28- Inlet tube of water.
- 29- Brass tube for thermostat.
- 30- Float.
- 31- Drain cock.
- 32- Crank.
- 33- Drive spring.
- 34- Disk drive.
- 35- Rod drive.
- 36- Galvanized iron star.
- 37- Inlet power cable set.
- 38- Delta cable set.
- 39- Cover for lateral conductor set.
- 40- Intermediate toothed pulley (little).
- 41- Cooling coil.
- 42- Cooper bridge between phases.
- 43- Cooper terminal of contactor.